Ellis Island, Greenhouse
(U.S. Immigration Station, Greenhouse)
(Statue of Liberty National Monument)
New York Harbor
New York
New York
New York
New York

HARS. NY 31-ELLIS, 1A-

HABS No. NY-6086-A

#### **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Mid-Atlantic Region National Park Service
Department of the Interior
Philadelphia, Pennsylvania 19106

# HISTORIC AMERICAN BUILDINGS SURVEY UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HATES MY 31-ELLIS 1A-(Page)

7 February 1985

## ARCHITECTURAL DATA FORM

STATE NEW YORK	NEW Y	ORK	NEW YORK	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) HABS NO.				
ELLIS ISLAND, GREENHOUSE				NY-6086-A
SECONDARY OR COMMON NAMES OF STRUCTURE				
U.S. Immigration Station, Greenhouse				
Statue of Liberty National Monument COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
New York Harbor				
DATE OF CONSTRUCTION (INCLUDE SOURCE)  ARCHITECT(S) (INCLUDE SOURCE)				
1935 (Historic Structure Report by Harlan   Lord & Burnham Co., D. Unrau, 1981, pp. 590-92)   Manufacturers (NPS/1				
D. Unrau, 1981, pp. 590-92) Manufacturers (NPS/DSC Drawing 462/41,931) SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
The greenhouse was built for the purpose of propogating all the flowering plants on Ellis				
Island. It replaced a deteriorating greenhouse located north of the Main Building.				
It was built by the B & Z Contracting Company.				
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Standard greenhouse structure: angle				
iron frame, trusses and pipe columns. Five steel trusses and two longitudinal angle braces support the wood framing for glazing of the gable roof. Other features include (continued)				
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHEO FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
Rectangular, 51' x 25'-2" (see print of drawing filed with Field Records)				
EXTERIOR FEATURES OF NOTE The north and south ends are fifteen lights wide and the east and west sides consist of six wood-framed awning windows of six lights each. The wood door on the south end has nine intact upper lights and three wood panels. In front of the entry door is a small square vestibule, with a three foot high concrete wall above a (continued)				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The flooring is concrete.				
Tables consisting of wood frames, pipe legs and metal corners line the perimeter with two				
long tables down the center. A narrow room at the north end is formed by a glass wall and				
doorway. A table is intact along the north wall, and on the south wall is (continued)				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
None				
PRESENT CONDITION AND USE				
Vacant, deteriorated and planned for demolition.				
OTHER INFORMATION AS APPROPRIATE				
See Field Records.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
The former U.S. Immigration Station on Ellis Island is administratively part of the Statue				
of Liberty National Monument, National Park Service. The greenhouse was studied as part of the overall restoration/rehabilitation activities at Ellis Island. See bibliography.				
COMPILER, AFFILIATION DATE				

Beyer Blinder Belle, Architects & Planners

ELLIS ISLAND, GREENHOUSE (U.S. Immigration Station, Greenhouse) HABS No. NY-6086-A (Page 2)

MATERIAL OF CONSTRUCTION (continued) a four foot concrete base wall and copper capping on the plain wood ridge.

### EXTERIOR FEATURES OF NOTE (continued)

red quarry tile floor. All framing above the wall has been destroyed and the weathered door to this vestibule leans against one side. See following data pages and Field Records.

INTERIOR FEATURES OF NOTE (continued) another short table and a basin sink. See following data pages and Field Records.


#### **BIBLIOGRAPHY**

- Beyer Blinder Belle. "Historic Structures Report; Unit One; Ellis Island Statue of Liberty National Monument." Preliminary Draft. Prepared for the National Park Service, 1985.
- Building Conservation Technology/The Ehrenkrantz Group. "Historic Structures Report; Ellis Island Statue of Liberty National Monument New York." Prepared for the National Park Service, 1978.
- U.S. Department of the Interior, National Park Service, Denver Service Center. "Historic Structure Report; Ellis Island; Historical Data." Authored by Harlan D. Unrau, May 1981.
- . "Survey of Structures; Unit One; Greenhouse." Measured drawings (see data pages and Field Records).


ELLIS ISLAND, GREENHOUSE

(U.S. IMMIGRATION, GREENHOUSE)

HABS No. NY-6086-A (Page 3)




ELLIS ISLAND, GREENHOUSE)
(U.S. INSTERATION STATION, GREENHOUSE)
HABS No. NY-6086-A (Page 4)



ELLIS ISLAND, GREENHOUSE


(I.I. IMMIGRATION STATION, GREENHOUSE)

HABS No. NY-6086-A (Page 5)




ELLIS ISLAND, GREENHOUSE (U.S. IMMIGRATION STATION, GREENHOUSE)


HABS No. NY-6086-A (Page 6)




Greenhouse, view northwest, World War II, U.S. Immigration and Naturalization Service.



Greenhouse, view north, World War II, U.S. Immigration and Naturalization Service.



Greenhouse, view northwest, World War II, U.S. Immigration and Naturalization Service.



Greenhouse, interior, view north, World War II, U.S. Immigration and Naturalization Service.